
## **Metric Nut Sizes**



**IMPORTANT:** Make sure to print this chart to Actual Size (no scaling). After printing, measure the ruler in the margin to ensure correct scale.

mm =